=``]bc]gʻ8 YdUfha YbhcZHfUbgdcfhUh]cb Ghfi Whi fYgʻ±b2cfa Uh]cbʻA UbU[Ya YbhGnghYa Ghfi Whi fY'Gi a a UfmFYdcfh

Date: 11/04/2009 Page:

Structure Number: 047-0053 District: 3

Route #3:

Structure Number	r: 047-0053	District: 3									
			Inventory	y Data							
Facility Carried:	IL 47	Bridge Name:			Sufficiency Rating:	100.0	Structure Length:	137.7			
Feature Crossed:	BLACKBERRY CK.	Location:	1 M N OF US 34		HBRRP Eligible:	No	AASHTO Bridge Length	n: 99.9			
Bridge Remarks:	REVISED ITEM 43A FROM 2 TO 5 PER	R 1/5/99 OPERATIONS	S MEMO.		Replaced By:	000-0000	Length of Long Span:	62.0			
Bridge Status:	1 OPEN - NO RESTRICT	Status Date:	06/1994		Replaces:	047-0008	Bridge Roadway Width	: 44.0			
Status Remarks:					Last Update Date:	06/19/2009	Appr Roadway Width:	44.0			
Maint County:	047 KENDALL	Maint Township:	02 BRISTOL		Parallel Structure:	None	Deck Width:	47.2			
Maint Responsibility:	01 I.D.O.T.	-			Multi-Level Structure Nbr:		Sidewalk Width Right:	0.0			
Service On/Under:	1 HIGHWAY	5 / N	WATERWAY		Skew Direction: L	Left	Sidewalk Width Left:	0.0			
Reporting Agency:	1 I.D.O.T BUREAU OF MAIN	TENANCE	S	Skew Angle:	20 D 30 M 00	S	Navigation Control:	0 No			
Main Span Matl/Type:	5 PRESTRESS CONCRETE	/ (02 STRINGER/MULTI-BE	EAM/GIRDER	Structure Flared:	No	Navigation Horiz Clear:	0			
Nbr Of Main Spans:	3 Nbr Of Approac	h Spans: 0			Historical Significance:	No	Navigation Vert Clear:	0			
Approaches					Border Bridge State:		Culvert Fill Depth:	0.0			
Near #1 Matl/Type:		/			Bdr State SN:		Number Culvert Cells:	0			
Near #2 Matl/Type:		/			Bdr State % Responsibility:	0	Culvert Opening Area:	0.0			
Far #1 Matl/Type:		/			Structural Steel Wt	0	Culvert Cell Height:	0.00			
Far #2 Matl/Type:		/			Substructure Material:		Culvert Cell Width:	0.00			
Median Width/Type:	0 Ft. / 0 None			Rated By	: 2 IDOT	Rate Met	hod: 1 LOAD	FACTOR			
Guardrail Type L/R:	1Steel Plate Beam / 1	Steel Plate Beam	Inventory Rating:	36.	7(266) Load Rating Date	: 06/17/199	Railroad (Crossing Info			
Toll Facility Indicator:	0 No Toll		Operating Rating:	5	5(299)		Crossing 1 Nbr:				
Latitude:	41 D 40 M 18.85 S Longitud	e: 88 D 26	M 18.85 S	Design Lo	oad: 02 HS20		Crossing 1 Nbr:				
Deck Structure Type:	A CIP CON NRMLLY FORM		Deck Struc	cture Thicknes	ss: 7.5 SD : N FO : N		RR Lateral Underclear:	0.00			
Sidewalks Under Struc	cture:				F	R Vertical U	nderclear: 00 Ft	00 In			
	Key Route On Da	ta		Key Route Under Data							
Key Route Nbr: FEDE	RAL-AID PRIMARY 0326	Station: 00	03.520			Stati	on:				
Appurtenances Main F	Route 00.000	Segment:				Segr	ment:				
Inventory County: 0	947 KENDALL	Linked: Y				Link	ed:				
Township/Road Dist	02 BRISTOL N	atl. Hwy System: O	n NHS			Natl.	Hwy System:				
Municipality 6405	YORKVILLE Ir	ventory Direction:				Inve	ntory Direction:				
Urban Area: 1051	1051 C	urr AADT Yr/Count:	2007 / 16100			Curr	AADT Yr/Count:	/			
Functional Class: 3	OTHER PRINCIPAL ARTERIAL	st Truck Percentage:	16			Est T	Truck Percentage:				
** CLEARANCES ** So	outh/East North/West N	umber Of Lanes:	2	South/East	North/West	Num	ber Of Lanes:				
Max Rdwy Width: 0)44.0 O	ne Or Two Way:	2 Two-Way			One	Or Two Way:				
Horizontal: 0	045.3 000.0 B	ypass Length:	0			Вура	ass Length:				
	F	uture AADT Yr/Cnt:	2027 / 24300			Futu	re AADT Yr/Cnt:	/			
	D	esignated Truck Rte:	CLASS II			Desi	gnated Truck Rte:				
Lateral:	S	pecial Systems:	Yes			Spec	cial Systems:				
	*** Marked Route On I	Data ***			*** Marked Ro	ute Under	Data ***				
	Designation	Kind	Number		Designation		Kind	Number			
Route #1: 1 Mainli	•	Highway	0047		_						
Route #2:		- •									

=``]bc]g'8 YdUfha YbhcZHfUbgdcfhUh]cb Ghfi Wii fYg'=bZcfa Uh]cb'A UbU[Ya YbhGnghYa Ghfi Wii fY'Gi a a UfmFYdcfh

Date: 11/04/2009

Page: 2

Structure Number: 047-0053 District: 3

Data Related to Inspection Information																	
*** Inspe		*** Maximum Allowable Posting Limits ***								Bridge Posting Level:							
Routine NBIS:	48 MOS	Underwater:	0 MOS	One Tr	uck At A Time:			Combination Type 3S-1:		Ton	is	5	No Po	sting Re	quired		
		Special:	N	Single	Unit Vehicles:		Tons	C	ombinat	ion Ty	pe 3S-2	Ton	ıs				
					Inspection/Ap	pprais	sal Informa	atio	n								
Inspection Date:	02/	25/2009 Inspection	Temperature:		35Deg. F	F								** Ac	tual Po	sted Lin	nits **
Deck:	8	VERY GOO	DD CONDITION	- NO PRO	BLEMS NOTED								Single Unit Ve	hicle	s:		Tons
Superstructure:	8	VERY GOO	DD CONDITION	- NO PRO	BLEMS NOTED								Combination 7	Гуре	3S-1:		Tons
Substructure:	8	VERY GOO	DD CONDITION	- NO PRO	BLEMS NOTED								Combination 7	Гуре	3 S-2 :		Tons
Culvert:	N	NOT APPL	ICABLE										One Truck At	A Tin	ne:		
Channel and Protectio	n: 8	VERY GOO	DD CONDITION	- NO PRO	BLEMS NOTED		Deck Wearin	ng S	urf:	Α	BARE DECK N	NO OVR	RLAY	Last	Paint Ty	уре:	
Structural Evaluation:	8	EQUAL TO	PRESENT DES	SIRABLE C	RITERIA		Deck Membr	rane	:	F	NONE						
Deck Geometry:	6	EQUAL TO	PRESENT MIN	IMUM CRI	TERIA		Deck Protect	tion	:	Α	EPOXY COAT	ED REI	NF				
Underclearance-Vert/L	at.: N	NOT APPL	ICABLE				Total Deck T	Γhicl	k:	07.5	5						
Waterway Adequacy:	8	EQUAL TO	PRESENT DES	SIRABLE C	RITERIA		Last Paint D	ate:									
Approach Roadway Al	ign: 8	EQUAL TO	PRESENT DES	SIRABLE C	RITERIA												
Bridge Railing Apprais	al: 3	Meets Stan	dards														
Approach Guardrail:	332	Acceptable	Accepta	able	Not Acceptable												
Pier Navig Protection:	N	N/A															
Underwater Inspection/Appraisal Information																	
Inspection Date: Temperature:		Inspection (

Appraisal Rating:

		Scour Critical	Information		Miscellaneous						
Rating: 8	B CALCULAT	ED SCOUR ABOVE FOOTING	Evaluation Method:	В	Rational Analysis						
Analysis Date:	alysis Date: 07/08/1999					Microfilm Data Recorded: Yes					
		Construction Information				Waterwa	y Information				
Year:	1994 Original	F	Reconstructed	Floo	od Design Frequency:	0 YF	RS Drainage Area:	0	Acre		
Route:	FAP 326	Sta : 865+53	Sta:	Flo	od Design Q (CFS):	0					
Section Nbr:	108 BR			Flo	od Design Nat H W E:	0	Flood Base Q (CFS):	0			
Contract Nbr:	86427			Flo	od Des Open Prop:	0 S	F Flood Base Nat H W E:	0			
Fed Aid Pr#:											
Built By:	1 I.D.O.T.										